Discreet Smoke: Cannot load 1920x1154_72

Published 07/30/2004

Symptom(s):

SYSLOG error: "unix: ALERT: odsy board 0: odsy_LoadDCD2Regs(): Failed to write to DCD2 Output control (0x0)"
SYSLOG error: "unix: WARNING: odsy board 0: odsyLoadTimingTable() LoadDCD2Regs failed"
SYSLOG error: "unix: ALERT: odsy board 0: odsyLoadTimigTable(): abnormal return"
SYSLOG error: 'Xsgi0[1099]: odsyLoadTimingTable: ODSY_LOAD_TIMING_TABLE Failed 'Resource busy''
SYSLOG error: 'Xsgi0[1099]: odsyLdFmtByName: odsyLoadTimingTableFailed'
SYSLOG error: 'Xsgi0[1099]: odsyBlankScreen: ODSY_BRDMGR_SET_BLANKING failed: 'Resource temporarily unavailable''
Discreet application will not load 72Hz resolution
Loading 1920x1154_72 fails sometimes

Fact(s):

SGI Tezro
Discreet Smoke 6.0.2
1920x1154_72
Trying to change resolution from within Smoke

SGI Solution:

Discreet have logged a bug against their combination file containing the VFO.

Change(s):

Tried to change the resolution within Smoke to 1920x1154_72

Additional Details

Creation Date	07/27/2004 10:14 AM
Last modification	01/15/2016 04:29 PM
Published Date	07/30/2004
Products	• Servers and Clusters • SGI Origin/Onyx • Origin/Onyx Server • Workstations • SGI Tezro • O2 • Octane
Categories	• Knowledgebase • Technical Solution